

Kings : North Clinton St.



Residential : 105 Sabine St.



Residential : 239 Merriman Ave.

It becomes blatantly obvious based on the level of care taken to maintain front door appearances which income level zone you may be in. Front doors which are poorly maintained are present in areas within the city that house lower income families.

These areas also contain many abandonded buisnesses as well.

Abandonded : 506 Oswego St.

My study from my first experience compared to the second time doing this project varried a bit. The first time doing this project I was focused solely on the appearance of the front door. This provided me with a lot of information but I felt that more context was needed to fully understand the present conditions.

In my second attempt to understand the level of care in relation to income level, I still photographed front doors, however it was done with much more context taken around it. Certain things such as overgrown lawns or broken windows added to the overall feel and character of the building.

Barber Shop : 120 Walton St.

MOST : West Jefferson St.

Residential : 602, 604 Oswego St.

Residential : 703 Niagara St.

Residential : 222 Merriman Ave.

205
UNITED UNIFORM
800
A Xerox Company
1224
1748
POR SALE

PRESENT CONDITIONS - DOORS: BY SEAN PATRICK KERNAN

THE INTENT OF THIS PROJECT WAS TO DOCUMENT DIFFERENT CONDITIONS WHICH ARE PRESENT AT BUISNESS AND RESIDENTIAL FRONT DOORS IN SYRACUSE, NEW YORK. THE CONDITIONS WHICH WERE PRESENT VARIED DEPENDING ON THE LOCATION WITHIN THE CITY. WHETHER OR NOT THE ESTABLISHMENT WAS OCCUPIED OR NOT HAD A DIRRECT EFFECT ON THE CONDITIONS OF THE FRONT DOOR. A MAP IS LOCATED AT THE BOTTOM RIGHT OF THE POSTER WHICH SHOWS THE EXACT ROUGHT WHICH WAS FOLLOWED FOR THIS DOCUMENTATION.